


Index No. P 21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 23 Corner common to sections 23, 24



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1874  
Original monument lost

Species	Bearing	Trees
<u>Aspen</u>	<u>Aspen</u>	
Diameter <u>2 1/2 E</u>	<u>3"</u>	
Bearing <u>N30W</u>	<u>S87E</u>	
Distance <u>2545</u>	<u>6245</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Distance

**Subsequent Corner Restoration**

Year surveyed 1933 by GLO  
Location filed Sec. of State  
Monument Find SE bit. (down) set 1x36" 1/4 Pine/brush  
cap  
523/524  
1933

**Evidence of Subsequent Corner Restoration**

Year of search 1966 By William Okerman  
found GLO monument in good condition.

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
<u>Poplar</u>	<u>Poplar</u>	
Diameter <u>5"</u>	<u>5"</u>	
Bearing <u>S47E</u>	<u>N51W</u>	
Distance <u>945</u>	<u>1645</u>	

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
<u>Elm</u>	<u>Ash</u>	
Diameter <u>12"</u>	<u>7"</u>	
Bearing <u>S169E</u>	<u>S12E</u>	
Distance <u>124.0'</u>	<u>26.2'</u>	

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_