


Index No. R 13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1879
Original monument bst

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>Limd</u>	<u>Limd</u>	<u>Elm</u>	<u>Limd</u>
<u>8"</u>	<u>7"</u>	<u>12"</u>	<u>8"</u>
<u>N45E</u>	<u>S85E</u>	<u>S70W</u>	<u>N9W</u>
<u>29US</u>	<u>19US</u>	<u>19US</u>	<u>29US</u>

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1933 By GLO
Location filed Sec. of State
Monument End NE, SE & SW BITS - now 14" 12" & 14"
Set concrete man 24" long 6" dia w/ brass cap T145NR3W
521/522
528/527

Evidence of Subsequent Corner Restoration

Year of search 1970 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Elm</u>	<u>Y. Birch</u>	<u>B. Ash</u>
<u>7"</u>	<u>17"</u>	<u>6"</u>
<u>N58 3/4 E</u>	<u>S40 1/2 E</u>	<u>S73 3/4 W</u>
<u>40 US</u>	<u>42 US</u>	<u>24 US</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. Pine</u>	<u>Elm</u>	<u>B. Ash</u>
<u>25"</u>	<u>7"</u>	<u>7"</u>
<u>S62W</u>	<u>N53W</u>	<u>N33E</u>
<u>82.80'</u>	<u>45.60'</u>	<u>28.60'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Bill Okerman - 1970

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____