


Index No. R.0-22.6

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

M.C. #9 Corner common to sections 24, 25



25

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search 1933 by Bandy
Monument found _____

Dependent Resurvey

Bearing Trees

Species	<u>Tamarack</u>	<u>White Pine</u>	_____
Diameter	<u>12"</u>	<u>10"</u>	_____
Bearing	<u>N 52° W</u>	<u>S 88° W</u>	_____
Distance	<u>96 links</u>	<u>100 links</u>	_____

Original Bearing Trees Found

Species	<u>Tamarack</u>	<u>White Pine</u>	_____
Diameter	<u>fallen</u>	<u>stump</u>	_____
Bearing	<u>N 52° W</u>	<u>S 88° W</u>	_____
Distance	<u>96 links</u>	<u>100 links</u>	_____

Subsequent Corner Restoration

Year surveyed 1900-03 By T.M. Fowble, COE
Location filed: Leech Lake and Winnibigoshish Reservoir Map
Monument: Map indicates a known corner.

Evidence of Subsequent Corner Restoration

Year of search 1/1931 By O.R. Boeruer, CCC
Location filed: USFS Form 874
Monument: Stake 20" above ground

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1933 By W.W. Bandy, Surveyor
Location filed: Resurvey, MN Historical Society T145N
Monument: Set 1"x 36" Iron pipe w/brass cap S24
from remains of original witness trees S25 MC
36" White Pine, N 3° W, 215 links R30W
6" Ash, S 87 1/2° W, 118 links 1933

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

1/1986, C. Krause, USFS
USFS Book 1, page 29
GLO pipe lying on ground. Set 50d spike from 1933 witnesses.
40" White Pine, N 3° W, 141.90' (1933) windfall
12" Ash, S 88° W, 77.88' (1933)
9" Ash, N 59° W, 16.25'

5/1986, C. Krause, USFS
USFS Book 1, page 29
Reset GLO brass cap in place of 50d spike, flush, on shore line, add witness.
8" Ash, N 3° E, 46.1'

