


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

E 1/4 28 Corner common to sections 27, 28



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Dead Birch</u>	<u>Dead W. Pine</u>	_____
Diameter	<u>24"</u>	<u>30"</u>	_____
Bearing	<u>N 10° W</u>	<u>S 20° E</u>	_____
Distance	<u>40 links</u>	<u>8 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed Circ 1930 By CCC
Location filed: USFS Form 874-9
Monument: 4" Jack Pine post

Evidence of Subsequent Corner Restoration

Year of search 7/1933 By W.W. Bandy, Surveyor, GLO
Location filed: MN Historical Society, Notes pg 60 1/4
Monument: Set 1"x 3' iron pipe with brass cap S 28 | S 27
at proportionate distance, no remaining evidence 1933
of original post or bearing trees, up 9" and
witnessed as follows.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Burr Oak</u>	<u>White Pine</u>	_____
Diameter	<u>6"</u>	<u>10"</u>	_____
Bearing	<u>N 32° E</u>	<u>S 33 1/4° W</u>	_____
Distance	<u>17 links</u>	<u>19 links</u>	_____

Subsequent Corner Restoration

Year surveyed 10/1970 By C.R. Krause, USFS
Location filed: USFS Book 2, page 33
Monument: Found GLO brass cap iron pipe
up 10", Blue line N-S and E-W, N-S line is blazed, witnesses.
10" Burr Oak, N 32° E, 11.2'(1933) rescribed FS 54-4 sign
22" White Pine, S 33° W, 12.5'(1933) rescribed FSLP added
25" White Pine, S 20° E, 32.3' scribed


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. T13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 28 Corner common to sections 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1879
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Dead Birch Dead White
Diameter 24" 30"
Bearing N10W S20E
Distance 40 LKS 8 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1933 By GLO
Location filed Sec. of State
Monument Set 1x36" l.p. willow cap 1/4
528/527
1933

Evidence of Subsequent Corner Restoration
Year of search 1970 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects
Species Br. oak willow
Diameter 6" 10"
Bearing N32E S33 1/2 W
Distance 17 LKS 19 LKS

Bearing Trees, Reference Objects
W. Pine B. Oak
25" 10"
S20E N32E
32.30' 11.20'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1970

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____