


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 26 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>White Pine</u>	_____
Diameter	<u>8"</u>	<u>6"</u>	_____
Bearing	<u>N 88° E</u>	<u>S 70° W</u>	_____
Distance	<u>12 links</u>	<u>30 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1900-03 By T.M. Fowble, COE
Location filed: Leech Lake and Winnibigoshish Reservoir Map
Monument:
Map indicates a known corner.

Evidence of Subsequent Corner Restoration

Year of search 7/1933 By W.W. Bandy, Surveyor, GLO
Location filed: Resurvey Notes, MN Historical Soc. 1/4
Monument: Set 1" OD iron pipe with brass cap S 26 | S 25
At proportionate position, no original evidence. 1933

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Poplar</u>	<u>Poplar</u>	_____
Diameter	<u>4"</u>	<u>5"</u>	_____
Bearing	<u>N 53° E</u>	<u>S 36 1/2° W</u>	_____
Distance	<u>30 links</u>	<u>25 links</u>	_____

Subsequent Corner Restoration

Year surveyed 1/1962 By R.H. McDonald, USFS
Location filed: USFS Book 1, page 26
Monument: Found GLO iron pipe with brass cap
S. of large clearing on a well marked E.-W. line and witnesses
11" Aspen, S 36° W, 16.50' (1933)
4" Oak, S 84° E, 41.55'
12" Aspen, N 65° W, 1.85'
Steel Sign Post, West, 2.23' 54-2 and 54-4

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____


9/1976, C.R. Krause, USFS
USFS Book 1, page 26
Found iron and cap, 1962 witnesses OK.

1/1986, C.R. Krause, USFS
USFS Book 1, page 26
Found GLO iron pipe with brass cap, up 1' in good condition,
S. if an open field, trail in field goes to FS #2932.
13" Poplar, S 37° W, 16.50' (1933) 10' stub
5" W. Oak, S 84° E, 41.55' (1962)
14" Poplar, N 65° W, 1.85' (1962) 8' stub
4" Maple, N 78° E, 13.75' 50d spike
7" Maple, S 53° W, 58.65' 50d spike
Steel Sign Post, West, 2.23' (1962) no signs

Index No. JR1

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 26 Corner common to sections 25, 26



O = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Aspen W. Pine
Diameter 8" 6"
Bearing N88E S70W
Distance 12 LKS 30 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1933 By GLO
Location filed Sec. of State
Monument Set 1x36" 11P. w/bress cap
11/1
526/525
1933

Evidence of Subsequent Corner Restoration
Year of search 1962 By Pete Meyer
Found GLO monument in good condition.

Bearing Trees, Reference Objects
Species Poplar Poplar
Diameter 4" 5"
Bearing N53E S36 1/2 W
Distance 30 LKS 25 LKS

Bearing Trees, Reference Objects
OAK Aspen
4" 12"
S84E N65W
41.55' 1.85'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____