


Index No. U 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S 1/16 Corner common to sections 25 AND 30-145-29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1933 S 1/16  
Original monument 1x36" l.b. willbress S 25/530  
cap 1933

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>	_____
Diameter	<u>10"</u>	<u>8"</u>	_____
Bearing	<u>S 18 1/4 E</u>	<u>S 58 3/4 W</u>	_____
Distance	<u>35 LKS</u>	<u>46 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1962 By PETE MEYER  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Elm</u>	_____
Diameter	<u>10"</u>	<u>6"</u>	_____
Bearing	<u>S 42 W</u>	<u>N 53 1/2 E</u>	_____
Distance	<u>32.8'</u>	<u>5.1'</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Cert. Ficate - Pete Meyer 1962

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_