


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 31 Corner common to sections 30, 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search 1933 by Bandy
Monument found _____

Resurvey notes page 80

Bearing Trees

Species Aspen White Pine
Diameter 4" 24"
Bearing N 42° W S 52° E
Distance 1 links 47 links

Original Bearing Trees Found

Species Dead W. Pine
Diameter 30"
Bearing S 52° E
Distance 47 links

Subsequent Corner Restoration

Year surveyed 8/1933 By W.W. Bandy, Surveyor, GLO
Location filed: MN Historical Society, Notes page 80
Monument: Set 6" concrete cylinder with brass cap S 30
from remains of original bearing tree, up 4" 1/4 _____
and witnessed as follows. S 31
1933

Evidence of Subsequent Corner Restoration

Year of search 5/1966 By M. Hansey, USFS
Location filed: USFS Book 2, page 19
Monument: Found GLO 2" iron pipe with brass cap
Not concrete monument as noted, decayed stump at original
Pine witness and witnessed as follows.

Bearing Trees, Reference Objects

Species Poplar Burr Oak
Diameter 10" 5"
Bearing N 42 1/2° W S 23 1/2° W
Distance 34 links 40 links

Bearing Trees, Reference Objects

Species Oak Oak
Diameter 8" (1933) 7"
Bearing S 24° W N 87° W
Distance 26.4' 18.0'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

