


T. 145 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search 1933 by Bandy  
Monument found \_\_\_\_\_

Resurvey Notes page 78

Bearing Trees

Species	White Pine	Yellow Pine	Yellow Pine	Yellow Pine
Diameter	14"	14"	20"	24"
Bearing	S 22° W	N 25° W	N 70° E	S 56° E
Distance	43 links	80 links	59 links	27 links

Original Bearing Trees Found

Species	N. Pine stump	W. Pine stump		
Diameter	30"	24"		
Bearing	S 56° E	S 22° W		
Distance	27 links	43 links		

Subsequent Corner Restoration

Year surveyed 12/1931 By P. Zeluyhoff, Estimator, CCC  
Location filed: USFS Form 874-9  
Monument:  
Intersection of lines.

Evidence of Subsequent Corner Restoration

Year of search 8/1933 By W.W. Bandy, Surveyor, GLO  
Location filed: MN Historical Society, Notes pg 78 T145N R30W  
Monument: Set 6" conc. cylinder with brass tablet S 30 | S 29  
from remains of original witnesses, up 4" S 31 | S 32  
and witnessed as follows. 1933

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Species	Poplar	Poplar	Burr Oak	Burr Oak
Diameter	12"	5"	5"	3"
Bearing	N 12 1/2° E	S 77° E	S 26° W	N 77° W
Distance	37 links	16 links	32 links	7 links

Subsequent Corner Restoration

Year surveyed 5/1966 By J. Ekstrom, USFS  
Location filed: USFS Book 2, page 24  
Monument: Found GLO concrete with brass tablet  
and witnesses as follows.  
5" Oak, S 26° W, 20.08'(1933) scribe overgrown  
5" Oak, N 77° W, 4.62'(1933) rescribed  
4" Oak, N 54° E, 20.0' scribed  
4" Oak, S 26° W, 8.8' scribed  
4" Maple, S 53° E, 23.8' scribed


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

Index No. V5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1874  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>W. Pine</u>	<u>Y. Pine</u>	<u>Y. Pine</u>	<u>Y. Pine</u>
Diameter	<u>14"</u>	<u>14"</u>	<u>20"</u>	<u>24"</u>
Bearing	<u>S22W</u>	<u>N25W</u>	<u>N70E</u>	<u>S56E</u>
Distance	<u>43US</u>	<u>80US</u>	<u>59US</u>	<u>27US</u>

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1933 By GLO  
Location filed Sec. of State  
Monument Find Stumps of SE & SW BITS Set Concrete  
MON 24" long 6" dia w/ brass cap T145N R30W  
S30/S29  
S31/S32  
1933

Evidence of Subsequent Corner Restoration  
Year of search 1966 By William Okerman  
Found GLO monument in good condition.

Species	Bearing Trees, Reference Objects			
	<u>Poplar</u>	<u>Poplar</u>	<u>Br. Oak</u>	<u>Br. Oak</u>
Diameter	<u>12"</u>	<u>5"</u>	<u>5"</u>	<u>3"</u>
Bearing	<u>N12 1/4 E</u>	<u>S77 E</u>	<u>S26 W</u>	<u>N77 W</u>
Distance	<u>37 US</u>	<u>16 US</u>	<u>32 US</u>	<u>7 US</u>

Bearing Trees, Reference Objects			
<u>Oak</u>	<u>Oak</u>	<u>Oak</u>	<u>Maple</u>
<u>5"</u>	<u>4"</u>	<u>4"</u>	<u>4"</u>
<u>N77W</u>	<u>N54E</u>	<u>S26W</u>	<u>S53E</u>
<u>4.62'</u>	<u>20.0'</u>	<u>8.8'</u>	<u>23.8'</u>

(1933 BT)

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_