


Index No. X-Y 21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
MC #4 Corner common to sections 35,36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

| Bearing Trees | |
|------------------------|---------------|
| Species <u>Tam</u> | <u>Cedar</u> |
| Diameter <u>10"</u> | <u>10"</u> |
| Bearing <u>S22E</u> | <u>N70E</u> |
| Distance <u>70 LKS</u> | <u>10 LKS</u> |

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| | | |
|----------------|-------|-------|
| Species _____ | _____ | _____ |
| Diameter _____ | _____ | _____ |
| Bearing _____ | _____ | _____ |
| Distance _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

| | | |
|----------------|-------|-------|
| Species _____ | _____ | _____ |
| Diameter _____ | _____ | _____ |
| Bearing _____ | _____ | _____ |
| Distance _____ | _____ | _____ |

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | |
|-------|-------|-------|
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____