


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

S 1/4 34 Corner common to sections 34 and 3-144-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument Post

Original Evidence Found

Year of search 1930 by Craig

Monument found _____

Resurvey notes page 11

Bearing Trees

Species White Pine Yellow Birch

Diameter 25" 7"

Bearing N 70° E N 35° W

Distance 32 links 15 links

Original Bearing Trees Found

Species White Pine

Diameter 36"

Bearing N 70° E

Distance 32 links

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, U.S. Surveyor, GLO

Location filed: MN Historical Society, Notes page 11

Monument: Set 1"x 3' iron pipe with brass cap from original bearing tree and marked new witness as follows. SC 1/4 S 34 1930

NE cor. Sec. 4-144-30 is S 89°31' W, 1.42 Chains(93.72')

Bearing Trees, Reference Objects

Species Poplar

Diameter 7"

Bearing N 51 3/4° W

Distance 30 links

Evidence of Subsequent Corner Restoration

Year of search 7/1934 By D.B. Rose, Compassman, CCC

Location filed: USFS Form 874-9

Monument: Found pipe with brass cap in good condition and witnesses as follow.

Bearing Trees, Reference Objects

Species Aspen White Pine

Diameter 8" 30"

Bearing N 52°30' W N 69 1/2° E

Distance 30 1/2 links 31 links

Subsequent Corner Restoration

Year surveyed 4/1964 By W.H. Okerman, LS 6807

Location filed: USFS Book 2, page 3

Monument: Found 1" iron pipe with brass cap and witnessed as follows.

16" Poplar, N 50° W, 20.1'(1930) scribe overgrown

36" White Pine, N 70° E, 21.1' scribe visible

7" Birch, N 71° W, 14.5' scribed

9" Birch, N 16° E, 48.3' scribed

6" Birch, S 66° E, 5.0' 54-4 sign

4/1991, G. Brama, USFS

USFS Book 2, page 3

Found 1" iron pipe with brass cap, up 7", 15', S. FS rd. #2932, 1930 witnesses are gone, 1964 witnesses are snags, new witnesses as follow.

8" Ash, N 39° W, 68.35' scribed

5" Ash, N 18° W, 58.85' scribed

7" Yellow Birch, N 30° E, 82.02' scribed

Steel Sign Post, North, 2.4' 54-4 sign attached

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____


Location filed: _____

Monument: _____

Index No. 215

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
S1/4 34 Corner common to sections 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species W. Pine Y. Birch
Diameter 25" 7"
Bearing N70E N35W
Distance 32 Lks 15 Lks

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By GLB
Location filed Sec. of State
Monument Find NE B.T. - now 36" - set 1x36" I.P. with brass cap
SC
14534
1.42 CH. N89-31W From 413
1930

Evidence of Subsequent Corner Restoration

Year of search 1964 By William Okerman
Found GLB monument in good condition.

Bearing Trees, Reference Objects

Species Poplar
Diameter 7"
Bearing N51 3/4 W
Distance 30 Lks

Bearing Trees, Reference Objects

Birch Birch Birch
7" 9" 6"
N71 W N16 E S16 E
14.5' 48.3' 5.0'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1964

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____