


Index No. A 11-12

CASS COUNTY LAND CORNER RECORD

T. 14S R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 26 Corner common to sections 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Bearing Trees	
Species <u>Tam</u>	<u>19m</u>
Diameter <u>6"</u>	<u>4"</u>
Bearing <u>S23W</u>	<u>N88W</u>
Distance <u>33 lks</u>	<u>43 lks</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1932 By H. Craig, GLO  
Location filed Beltrami Co.  
Monument Found nothing, set 35.29  
W. of A-13, 3 Iron post 1" Dia 28" in  
ground with brass cap.

Bearing Trees, Reference Objects

Species <u>Tam</u>	<u>Cedar</u>
Diameter <u>7"</u>	<u>5"</u>
Bearing <u>S69 3/4° E</u>	<u>N43 1/4° W</u>
Distance <u>158 lks</u>	<u>47 lks</u>

Evidence of Subsequent Corner Restoration

Year of search 2006 By Murray  
Found

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_