


Index No. A 15-16

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
M.C. # 12 Corner common to sections 3



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Species	<u>Aspen</u>	Bearing	<u>OnK</u>	Trees	_____
Diameter	<u>7"</u>		<u>10"</u>		_____
Bearing	<u>S26W</u>		<u>N79W</u>		_____
Distance	<u>56 LKS</u>		<u>105 LKS</u>		_____

Original Evidence Found

Year of search 8/1972 By HOEST  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	<u>POPULAR</u>	_____	_____
Diameter	_____	_____	_____
Bearing	<u>S26°W</u>	_____	_____
Distance	<u>1/2</u>	_____	_____

BEADEN / BLAZE VISIBLE, CURD BK 186 Pg 5 (M/F)

Subsequent Corner Restoration

Year surveyed 1964 By DNK-Engineering  
Location filed Map & notes in file  
Monument Found non set by Beltrami Co. Engineer  
On E-W fence

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_