


Index No. A.0-19.0

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

N 1/4 2 Corner common to sections 2 and 35-146-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search 1900 by COE  
Monument found \_\_\_\_\_

Lake Winnebigoishish Reservior

Bearing Trees

Species	<u>Norway Pine</u>	<u>Norway Pine</u>	_____
Diameter	<u>16"</u>	<u>30"</u>	_____
Bearing	<u>S 16° E</u>	<u>N 38° E</u>	_____
Distance	<u>21 links</u>	<u>47 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1904 By T.M. Fowble

Location filed: Lake Winnebigoishish Reservior

Monument:  
Indicates known corner

Evidence of Subsequent Corner Restoration

Year of search 4/1931 By J.M. Greene

Location filed: Curo Book 61, image 111

Monument:  
Indicates a Temp 1/4 Cor and True 1/4 Cor S 7°51' E, 90.9' from Temp 1/4 Cor.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1933 By H.D. Craig, U.S. Surveyor

Location filed: Minnesota Historical Society 1/4 S35

Monument: Set 1"x36" I.P. w/brass cap S2  
at proportionate position, no original evidence. 1933

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

