


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____

Original Evidence Found

Year of search _____ by _____
 Monument found _____

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:


Year of search _____ By _____
Location filed:
Monument:

Index No. A 5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X _____ Y _____

NE 6 Corner common to sections 3, 6



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1875
Original monument lost

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>Nilme</u>	<u>Nilme</u>	<u>Nilme</u>	<u>Aspen</u>
Diameter <u>14"</u>	<u>20"</u>	<u>14"</u>	<u>6"</u>
Bearing <u>S 85 E</u>	<u>S 65 W</u>	<u>N 34 W</u>	<u>N 62 E</u>
Distance <u>40 LKS</u>	<u>28 LKS</u>	<u>53 LKS</u>	<u>42 LKS</u>

Original Bearing Trees Found			
Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1915 By John Curo
Location filed County Resurvey Plat "E-67"
Monument 1 1/2 x 48" I.M.
1914, FA. Donner Book "C" P 92 Fnd I.P. set
BY Curo
- also on microfilm - roll 115 BK 94 P. 69-70

Year of search 1914 By Harry Todd
microfilm - roll 115 BK 74 P. 116
Fnd true corner - set an iron
1915 - Maloney - microfilm - roll 115 BK 82 P. 9
Fnd 1 1/2 x 48" I.M. set by Curo

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

