


T. 145 R. 31 M. 57 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.N. 116 Corner common to sections 2



O = Corner

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1933

Original monument Concrete man 2 6" long  
6" Dia w brass cap

**Bearing Trees**

Species	<u>Birch</u>	<u>5 in</u>
Diameter	<u>10"</u>	<u>6"</u>
Bearing	<u>N 13 3/4 E</u>	<u>N 62 1/4 W</u>
Distance	<u>10 LKS</u>	<u>56 LKS</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

**Bearing Trees, Reference Objects**

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

By \_\_\_\_\_ Date \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Remuneration certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Subsequent Corner Restoration