


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. C5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X _____ Y _____
E1146 Corner common to sections 5, 6



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Bearing Trees

Species	<u>N. Pine</u>	<u>J. Pine</u>	
Diameter	<u>16"</u>	<u>8"</u>	
Bearing	<u>N38E</u>	<u>S74W</u>	
Distance	<u>35 LKS</u>	<u>135 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURD
Location filed COUNTY RESURVEY PLAT "E-67"
Monument 1 1/2 x 48" IRON MONUMENT

1915 - Malvern - microp/m - roll 115 BK82 P. 9
End 1 1/2 x 48" IM SET by CURD

Evidence of Subsequent Corner Restoration

Year of search 1990 By WALT CURD
CASS Co. Hwy DEPT. SURVEY CREW
SET 2" x 2" x 6" TELESTAR PION/ALUM CAP
FLUSH WITH NEW BLACKTOP SURFACE

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>W. OAK</u>	<u>P. POLE</u>	<u>N. PINE</u>
<u>4"</u>		<u>2"</u>
<u>N 45 E</u>	<u>EAST</u>	<u>S 85 W</u>
<u>148.05</u>	<u>61.18</u>	<u>95.05</u>

Subsequent Corner Restoration C5

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CHPT. BY WALT CURD 1990
DOC. # 325741