


Index No. C9

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/4 S Corner common to sections 4, 5



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument lost

Bearing Trees
Species J. Pine J. Pine
Diameter 10" 4"
Bearing N59W S8E
Distance 106 LKS 264 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TODD
Location filed COUNTY SURVEY RECORD BOOK B P. 310-311
Monument FIND CORNER SET BY MIDDLETON, ALSO STUMP
OF OLD NW CORNER BIT,
1915, JOHN CURD, COUNTY RESURVEY PLAT 'E-67' 2 1/4 X 48' 2m.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1910 By JAMES MIDDLETON
COUNTY BOOK B P. 575 FIND 4" J. PINE HUB SET FROM
OLD CORNER BTS: 10" J. PINE N59W (DOWN) 106 LKS,
AND COUNTY RD. SURVEY TIES: 8" J. PINE N76-17W 161'40"
9" J. PINE S84-56E 60.07'

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

C-9

Subsequent Corner Restoration

Year surveyed 1915 By Maloney
Location filed microfilm - roll 115, BK 82 P. 20
Monument set I.M. proportionally

Evidence of Subsequent Corner Restoration Found

Year of search 1998 By Arthur Larson
RLS #14455 Certificate of survey
indicates iron monument found
2"

2/2001 - CCSO crew - found 2" ODIP
w/ plumbers cap, down 1.0', 3' E. of
E. Co. Rd #149. Witness as follows:

- P. Pole S 11° W, 121.84 *
- 11" Twin R. Oak, N 42° W, 98.89 *
- 5" N. Pine, N 36° E, 35.62 *
- Wood Post S 80° E, 29.4'
- * distance to double head nail

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____