

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_

Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Monument:


Certificate of Location of Government Corner filed in Cass County

Recorders Office as Document \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_

T. 145 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 B Corner common to sections 5, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Species	Bearing	Trees
<u>J Pine</u>	<u>J Pine</u>	
<u>8"</u>	<u>6"</u>	
<u>N63W</u>	<u>S28E</u>	
<u>8 LKS</u>	<u>25 LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1906 By JOHN CURO  
Location filed COUNTY SURVEY RECORD BOOK "A" P. 274-275  
Monument SET TRUE CORNER  
1915, JOHN CURO, COUNTY RESURVEY PLAT "E" - 67° 24' 48"  
1914, F.A. DANNER, BOOK "C" P. 92 FWD B.T. J. Pine T.M.  
N65-12W 28-20' SET HUB

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. Pine</u>	<u>N. Pine</u>	
<u>9"</u>	<u>9"</u>	
<u>S65W</u>	<u>S61-24E</u>	
<u>28.1'</u>	<u>94'</u>	

1915 TIES?

Evidence of Subsequent Corner Restoration

Year of search 1915 By MALYNEUX  
microfilm - roll 115 BK 82 P. 8, 19  
End Curo's hub pulled out P. 19 - Set hub  
1914 - also on microfilm - roll 115 BK 94 P. 66

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

(E 7)

Subsequent Corner Restoration

Year surveyed 11/01 By CCSO  
Location filed file # 2001, 043  
Monument found CIM, flush, 0.5' N. &  
CR # 60, add nails to 1993 BT's and  
following:  
11" N. Pine N39°E, 109.82 \* (1993)  
14" N. Pine S60°W, 123.06 \* (1993)  
8" N. Pine S39°E, 105.04 \*  
\* distance to db'l head nail

Evidence of Subsequent Corner Restoration Found

Year of search 1993 10-29 By Robert Murray  
Found bent & tipped over 2 1/4" capped pipe. Removed  
Placed MnDOT Cast Iron monument. Top of monument  
flush w/ highway surface. 4-26-94 Cert. Filed  
by Robert Murray, RLS 15483, Doc. 357108.  
Ties: 11" Norway N39E 109.85; 14" Norway  
S60W 122.87; 8" Norway S44E 88.37.

JUN 1996 K. DONAGHUE  
PLAT SHOWS MON FOUND