


T. 145 R. 31 M. 5TH Coordinates: X _____ Y _____
NW 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>Bl. Pine</u>	<u>Bl. Pine</u>	<u>Bl. Pine</u>	<u>Bl. Pine</u>
<u>0"</u>	<u>7"</u>	<u>9"</u>	<u>8"</u>
<u>533E</u>	<u>N75E</u>	<u>N65W</u>	<u>S11W</u>
<u>27LKS</u>	<u>49LKS</u>	<u>7LKS</u>	<u>57LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1993 10-25 By Robert Murray
Found 1" x 35" square, solid iron rod. Removed 10-25-93 placed a MnDOT cast iron monument. Top of monument 0.2' below surface 4-26-94
Cert. Filed by: Robert Murray, RLS 15483, Doc #257116

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Reference Object	Diameter	Bearing	Distance
<u>Garage Foundation</u>	<u>8"</u>	<u>9"</u>	
<u>NW corner</u>	<u>8"</u>	<u>9"</u>	
<u>N53E</u>	<u>53.710</u>	<u>S11E</u>	
<u>113.05</u>	<u>37.62</u>	<u>28.79</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
JUN 1996 X. DONAGHUE
PLAT SHOWS MON FOUND