


T. 14S R. 31 M. 5TH Coordinates: X _____ Y _____
NE16 Corner common to sections 9,10,15,16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Species	Bearing	Trees	Distance
<u>J Pine</u>	<u>J Pine</u>	<u>J Pine</u>	<u>J Pine</u>
<u>8"</u>	<u>7"</u>	<u>5"</u>	<u>8"</u>
<u>S22E</u>	<u>S49 1/2 W</u>	<u>N50W</u>	<u>N75E</u>
<u>110 LKS</u>	<u>91 LKS</u>	<u>61 LKS</u>	<u>66 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK "A" P. 178-219
Monument SET J.M. FROM 610 GAIT BITS.
1913, CURRO, BOOK "D" P. 153 FIND IRON CORNER - SET
1 1/2 X 4 1/8" GALV. CAPPED IR.
also on microfilm - roll 115 BK 74 P. 91-92

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

J-13

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - CASS LAKE
B.B. BARTLETT 1899

PLAT - ORIGINAL PLAT OF CASS LAKE
B.B. BARTLETT 1899

PLAT - VAN PELTS ADDITION TO CASS LAKE
JOHN CURO 1907

PLAT - PLAT OF WEST CASS LAKE
J.E. TAPKEY 1906

PLAT - PINE GROVE COMETARY - CASS LAKE
JOHN CURO 1914

1994 2-18: Placed P.K. nails around rim
of manhole.
4-26-94 Cert. Filed By: Robert Murray,
RLS 15483, Doc # 357122

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____