


Index No. K-L 21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 14 Corner common to sections 13,14



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1875  
Original monument bst

Species	Bearing	Trees
<u>W Pine</u>	<u>W. Ash</u>	
Diameter <u>12"</u>	<u>7"</u>	
Bearing <u>N30E</u>	<u>N41W</u>	
Distance <u>78 LKS</u>	<u>77 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species			
Diameter			
Bearing			
Distance			

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species			
Diameter			
Bearing			
Distance			

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species			
Diameter			
Bearing			
Distance			

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_ Date \_\_\_\_\_ Filed at \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument \_\_\_\_\_

Location filed \_\_\_\_\_

Year surveyed \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_