


Index No. M-13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5th Coordinates: X _____ Y _____
S 1/16 Corner common to sections 15 & 16



EXISTING SURVEYS

Original Government Survey
 Year surveyed _____
 Original monument _____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1987 By USFS
 Location filed Cass Co. Recorder #301990 (E 98)
 Monument Set USFS Brass cap, midway on line.

Evidence of Subsequent Corner Restoration
 Year of search 3/2001 By CCSO
Found USFS Brass cap, down oil, 1 1/2 E. of 9 CR #147. 1987 witnesses good, add the following:

Bearing Trees, Reference Objects			
Species	<u>R. Pine</u>	<u>J. Pine</u>	<u>Steel</u>
Diameter	<u>10"</u>	<u>9"</u>	<u>Post</u>
Bearing	<u>N51°E</u>	<u>N59°W</u>	<u>East</u>
Distance	<u>82.60'</u>	<u>44.25'</u>	<u>33.97'</u>

Bearing Trees, Reference Objects	
<u>Pin Oak</u>	<u>J. Pine</u>
<u>5"</u>	<u>12"</u>
<u>S38°W</u>	<u>S40°W</u>
<u>47.15'*</u>	<u>59.40'*</u>

* distance to double head nail

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
OCT 1987 W. OERMAN
CERT OF SVY SHOWS MON FOUND