


T. 145 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NW 31 Corner common to sections 30, 31 and 25, 36-145-32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Br. Oak</u>	<u>W. Pine</u>	<u>W. Pine</u>
Diameter	<u>9"</u>	<u>28"</u>	<u>30"</u>
Bearing	<u>N 4° E</u>	<u>S 7° W</u>	<u>N 6° W</u>
Distance	<u>53 links</u>	<u>62 links</u>	<u>301 links</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1973 By CCHD  
Location filed: Co. Rd. #69  
Monument: R.R. Spike

Evidence of Subsequent Corner Restoration

Year of search 8/1996 By Hubbard Co. Survey  
Location filed: Certificate of Location  
Monument: R.R. Spike

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Pop.</u>	<u>Pop.</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>20"</u>
Bearing	<u>NE</u>	<u>SE</u>	<u>ESE</u>
Distance	<u>139.8'</u>	<u>121.5'</u>	<u>117.2'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 9/1999 By G.E. Coulombe, LS 15810  
Location filed: Certificate of Location  
Monument: Set Hubbard Co. CIM  
add new witnesses  
Power Pole, N 65° E, 134.25' duplex nail, up 1.0', N. side  
Fence Cor. Post, S 50° E, 46.16' duplex nail, up 3.5', N. side  
Power Pole, S 45° W, 52.69' duplex nail, up 2.5', N. side  
Tel. Juct. Box, N 55° W, 66.06' top center

Evidence of Subsequent Corner Restoration Found


Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

10/2011, T.L. Freeman, LS 21367  
Certificate of Survey, #5761  
Indicates found CIM.

6/2016, CCHD/SO  
#2016.018  
Found CIM, down X.XX, on centerline Co. Rd. #69 and centerline Co. Rd. #76 and witnesses.

Index No. V 1

CASS COUNTY LAND CORNER RECORD



T. 145 R. 31 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NW 31 Corner common to sections 30, 31

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>Br. oak</u>	<u>Wilow</u>
Diameter	<u>9"</u>	<u>28"</u>
Bearing	<u>N 4E</u>	<u>S 7W</u>
Distance	<u>53 LKS</u>	<u>62 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1973 By Co Hwy Dept  
Location filed Co RD # 69  
Monument R. L. Spike

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>oak</u>	<u>Pop.</u>	<u>Pop</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>20"</u>
Bearing	<u>NE</u>	<u>SE</u>	<u>ESE</u>
Distance	<u>139.8</u>	<u>121.5'</u>	<u>117.2'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restordtion

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_