Index No. N 13-14

CASS COUNTY LAND CORNER RECORD

T. 146 R. 27 M. 5th Coordinates: X _____ Y _____

MC# 8 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument Cedar post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species NO TREES

Diameter

Bearing

Distance

Original Bearing Trees Found

Species

Diameter

Bearing

Distance

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species

Diameter

Bearing

Distance

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____