


Index No. R15

CASS COUNTY LAND CORNER RECORD

T. 146 R. 27 M. 5TH Coordinates: X _____ Y _____

N¹/₄ 27 - Corner common to sections 22, 27



○ = Corner

EXISTING SURVEYS

| Original Government Survey | Original Evidence Found |
|---------------------------------------|-------------------------------|
| Year surveyed <u>1874</u> | Year of search _____ By _____ |
| Original monument <u>Post (cedar)</u> | Monument found _____ |

| Bearing Trees | Original Bearing Trees Found |
|--------------------------|------------------------------|
| Species _____ | Species _____ |
| Diameter <u>NO trees</u> | Diameter _____ |
| Bearing _____ | Bearing _____ |
| Distance _____ | Distance _____ |

| Subsequent Corner Restoration | Evidence of Subsequent Corner Restoration |
|-------------------------------|---|
| Year surveyed _____ By _____ | Year of search _____ By _____ |
| Location filed _____ | _____ |
| Monument _____ | _____ |
| _____ | _____ |
| _____ | _____ |

| Bearing Trees, Reference Objects | Bearing Trees, Reference Objects |
|----------------------------------|----------------------------------|
| Species _____ | _____ |
| Diameter _____ | _____ |
| Bearing _____ | _____ |
| Distance _____ | _____ |

| Subsequent Corner Restoration |
|-------------------------------|
| Year surveyed _____ By _____ |
| Location filed _____ |
| Monument _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |

| Evidence of Subsequent Corner Restoration Found |
|---|
| Year of search _____ By _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |
| _____ |

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____