


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



± Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. V 4-5

CASS COUNTY LAND CORNER RECORD

T. 146 R. 29 M. 5TH Coordinates: X _____ Y _____
M C # 4 Corner common to sections 30, 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>Jilne</u>	<u>Jilne</u>
Diameter	<u>16"</u>	<u>12"</u>
Bearing	<u>N18W</u>	<u>S22W</u>
Distance	<u>53 LKS</u>	<u>123 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1934 By GLO
 Location filed Sec. of State
 Monument Set 1x36" lip. w/brass cap T146N
530 MC
531
R29W
1934

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Jilne</u>	<u>Jilne</u>
Diameter	<u>5"</u>	<u>8"</u>
Bearing	<u>S80 1/4 W</u>	<u>N17 1/2 W</u>
Distance	<u>124 LKS</u>	<u>102 LKS</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____