


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



± Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. V-W 9

CASS COUNTY LAND CORNER RECORD

T. 146 R. 29 M. 5TH Coordinates: X _____ Y _____
MC# 10 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument POST

Bearing Trees

Species	<u>Aspen</u>	<u>Birch</u>	_____
Diameter	<u>16"</u>	<u>12"</u>	_____
Bearing	<u>N85E</u>	<u>S81W</u>	_____
Distance	<u>9 LKS</u>	<u>20 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1935 By GLO
Location filed SEC. OF STATE
Monument set 1x36" 1/2" w/ brass cap

MC
532 533
T146N R29W
1934

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Juline</u>	_____
Diameter	<u>5"</u>	<u>3"</u>	_____
Bearing	<u>N74 1/2 W</u>	<u>N79 3/4 E</u>	_____
Distance	<u>36 LKS</u>	<u>44 LKS</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____