


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ by _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Location filed: _____

Monument: _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____


Location filed: _____

Monument: _____

Index No. Y 5

CASS COUNTY LAND CORNER RECORD

T. 146 R. 29 M. 5TH Coordinates: X _____ Y _____
51/16 Corner common to sections 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1934 51116
Original monument 1x36" 11P. w/bress cap 531/532 1934

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species J Pine J Pine _____
Diameter 6" 8" _____
Bearing S3E S50W _____
Distance 46LKS 42LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1963 By William Okerman
Location filed _____
Monument Found 6LO monument in good condition

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
BILL OKERMAN - CERTIFICATE - 1963