


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



± Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. 4-2-16

CASS COUNTY LAND CORNER RECORD

T. 146 R. 29 M. 57A Coordinates: X _____ Y _____
SMC ON Corner common to sections 34
E 1/4 Line



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1935 SMC
Original monument 1x36" 1.1 P.W. Dress E
cap S 134
E
1935

Bearing Trees

Species	<u>J. Pine</u>	<u>N. Pine</u>	_____	_____
Diameter	<u>6"</u>	<u>5"</u>	_____	_____
Bearing	<u>S 15 E</u>	<u>S 37 1/2 W</u>	_____	_____
Distance	<u>24 Yds</u>	<u>26 Yds</u>	_____	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

By _____ Date _____

Year of search _____ By _____

Evidence of Subsequent Corner Restoration Found

Remuneration certificate prepared _____

Filed at _____

Year surveyed _____ Location filed _____ Monument _____

Subsequent Corner Restoration