

U. S. Department of Agriculture
FOREST SERVICE

A-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 & 58 N R. 24 & 25 W 9th Mer.

Section Corner common to Sections
1, 6, 31, and 36

Corner consists of a 1" Iron Pipe (not) in place
State condition Good

Dimensions above ground 8 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 58 N
R. 24 W
5.31

T. 57 N
R. 24 W
5.6

[Empty box]

[Empty box]

B T

B. T.

[Empty box]

[Empty box]

Species W. Pine, Stump W. Pine, Stump

Diameter _____

Bearing N 59° E 58 50 E

Distance 27 lks 27 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by
County Surveyor.

Arthur J. Johnson

(Signature)

Guard Foreman

(Title)


2/15/20

(Date)

A-25

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 574 58 N R. 24 25 W 9th Mer.

U. S. Department of Agriculture
FOREST SERVICE

A-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57450N R. 29425W 1th Mer.

Section Corner common to Sections
1, 6, 31, and 36


Corner consists of a 2" Iron Pipe (not) in place
State condition

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T58N
R29W
5.31

T57N
R29W
3.6



B.T.

B.T.



Species W/ Pine Stump W/ Pine Stump

Diameter

Bearing N59°E S83°E

Distance 89ks 39ks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by County Surveyor

Arthur J. Johnson

(Signature)

2/15/190

(Date)

Special Foreman

(Title)

A-25

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

TITON R. BROWN 975