

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

L-15416

----- NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 R. 25 Mer.

----- Corner common to Sections
15, -----, and -----

Corner consists of a Iron pin - 3 sided (not) in place
 State condition good

Dimensions above ground 4" high inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
N	W	S	E	NW	SW	SE	NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>None</u>			

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

Ralph H. Christy
 (Signature)

7-14-34
 (Date)

D. F. M.
 (Title)

