

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

M-N-25

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 25 W. 4 th Mer.

Meander Corner common to Sections

13 - 57 - 25, and 18 - 57 - 24

Corner consists of a 3"x20" scribed Post in place



State condition Good

Dimensions above ground 20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Birch Elm

Diameter 17" 10"

Bearing S85°W S10°W

Distance 111 Lks 117 Lks

Do you believe this to be a genuine Land Office Corner? NO  
 If not, why? Records show it was set by  
 County Surveyor in 1925.

*Edward Pank*

11/21/39  
 (Date)

J. F. P. 1  
 (Signature) (Title)


M-N-25

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Corner again.

M.C. is 7.91 chains North of Corner 13 - 24, 57, 25 & 18 & 19, 57-24. South shore of Hanson Lake.

Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 57 N. R. 25 W. 4 th Mer.

U. S. Department of Agriculture  
 FOREST SERVICE

M-N-25

CHIPPENAW NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4 th Mer.

Meander Corner common to Sections

13 - 57 - 25, and 18 - 57 - 24

Corner consists of a 3x20" scribed post in place

State condition good

Dimensions above ground 20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	M.C. 318		M.C. 318
N		S	

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

GROWN  
OVERGROWN  
OVER

Species W. Birch Elm

Diameter 17" 10"

Bearing 85° W 810° W

Distance 111 lks 117 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by  
County Surveyor in 1925.

(Signature)

11/21/39

J. P. P. 1

(Date)


(Title)

MN-25

N. 6. is 7.51 chains North of Corner  
13 - 24, 57-25 & 18 & 19, 58-24. South  
shore of Hanson Lake.

Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N. R. 25 W. 4th Mer.