

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 & 27 W. 4th P. Mer.

1/4

Corner common to sections

1, and 6

Corner consists of a iron pipe & aspen post



State condition good

Dimensions above ground pipe 3/4 x 6, post 3 x 3 x 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? NO.

If not, why? Set by proportional measurement

No GLO corner found.

Signature of Seth Peterson

(Signature)


2/15/38

(Date)

Jr. Asst. to Tech.

(Title)

(Make sketch of topography near Corner)



T. 57N R. 26-27W 4th E. Mer.

Metal Location Poster is on a Aspen

tree $\frac{4}{4}$ inches diameter, on the West

side of 1 line

from which this Corner bears

0.04

chains distant.

Give any further facts which will aid in finding this

Corner again.