

U. S. Department of Agriculture
FOREST SERVICE

N-2

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 9th Mer.

W 1/16 Corner common to Sections
18, 19

Corner consists of a 4" scribed Post (not) in place

State condition Good

Dimensions above ground 90 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

W 1/16 S. 18		W 1/16 S. 19	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 18			
B. T.			

Species W. Pines. Stub W. Pines. Conv.

Diameter 8" 8"

Bearing N 90° W S 32° E

Distance 120 lks 161 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by
County Surveyor

Arthur T. Johnson

(Signature)

Special Foreman


(Title)

2/8/40
(Date)

N-2

Corner again.
This Corner lies 2.26 chains East of road
in brushy swamp. Can be seen fairly from road.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57N R. 26W 4th Mer.

U. S. Department of Agriculture

FOREST SERVICE

2-N

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 9th Mer.

W 1/6 Corner common to Sections

18, and 19

Corner consists of a 4" scribed Post (not) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

W 1/6			W 1/6
5.18			5.19

N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5.18			
B.T.			

Species W. Pine, Stub W. Pine (dnd)

Diameter 8" 8"

Bearing N 90° W S 82° E

Distance 120 lks 16 lks

Do you believe this to be a genuine Land Office Corner NO

If not, why? Records show it was set

set by County Surveyor

Arthur J. Johnson

(Signature)

Agued Farnham

(Title)

2/18/40


(Date)

N-2

This corner lies 2.36 chains
East of road in brushy marsh.
Can be seen plainly from road.

Corner again.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 52N R. 26W 4TH Mer.