

**U. S. Department of Agriculture**  
**FOREST SERVICE**

A 3

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 57-58 R. 26 4 Mer.

1/4

Corner common to Sections

31, 58, 26, and 6-57-26

Corner consists of a Cedar (mark) in place



State condition Poor

Dimensions above ground 48" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash

Diameter 12"

Bearing N. 18 E.

Distance 5 Links

Do you believe this to be a genuine Land Office Corner? Yes


If not, why?

6/13/36

(Date)

*O. J. Jones*  
(Signature)

(Title)



Corner again. In black with...

Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		
	Sec.		
	Sec. 31		
	Sec.		

(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

*Copy sent 8/1/36  
7/23/36*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. <sup>58-</sup>57- R. 26 4 Mer.

1/4 Corner common to Sections  
31, T 58, R 26, and 6-57-26

Corner consists of a Cedar (not) in place

State condition Poor

Dimensions above ground 48" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Illegible			
-----------	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

U			
---	--	--	--

BT			
----	--	--	--

Species Ash

Diameter 12"

Bearing N. 18 E

Distance 5 Links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*O. Lumbau*  
(Signature)

const. foreman


6/23/36

(Date)

(Title)

A-3

Metal Location Poster is on a n. Ash  
 tree 12 inches diameter, on the East  
 side of tree N. 5ch.  
 from which this Corner bears  
 S 5 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.  
 In black ash swamp.



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

A-3

NATIONAL FOREST

~~Chippewa~~  
 CORNERS OF THE PUBLIC SURVEY

T. ~~56~~<sup>58</sup>-N R. ~~26~~<sup>20</sup> W Mer. ~~4~~<sup>12</sup>

Corner common to Sections

1/4 31-58-26, and

6-57-26

Corner consists of a ~~stone~~<sup>Cedar</sup> in place

State condition ~~POOR~~<sup>POOR</sup>

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	Illegible		
--	-----------	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

U			

Species ~~BT~~<sup>Ash</sup>

Diameter ~~12"~~<sup>12"</sup>

Bearing ~~N. 16 E~~<sup>N. 16 E</sup>

Distance ~~5 Links~~<sup>5 Links</sup>

Do you believe this to be a genuine Land Office Corner?  Yes

If not, why? \_\_\_\_\_

*O. Linn*

(Signature)

CORNER FOREMAN

(Title)

6/23/36  
 (Date)

A-3

In black ash swamp.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears


side of

tree N. 60h.

tree 18 inches diameter, on the

East

Metal Location Poster is on a



(Make sketch of topography near Corner)