

U. S. Department of Agriculture  
FOREST SERVICE

N4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 9th Mer.

W. 1/16 Corner common to Sections  
18, and 19

Corner consists of a 1" scribed Post (not) in place  
State condition Good

Dimensions above ground 90 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

W 1/16		W 1/16	
S. 18		S. 19	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 18			
B. T			

Species W. Pine 5' to 6' W. Pine (dry)

Diameter 8" 8"

Bearing N 9° W S 82° E

Distance 130 lks 161 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by  
County Surveyor

Arthur J. Johnson

(Signature)

Special Foreman


(Title)

2/18/90

(Date)

Corner again.  
Corner lies 2.36 chains East of road in  
brushy swamp. Can be seen plainly from  
road.

Metal Location Poster is on a  
tree inches diameter, on the  
side of  
from which this Corner bears  
chains distant.



(Make sketch of topography near Corner)

T. 57N R. 26W 9th Mer.