

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

C-5

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 W. 4th P. Mer.

1/4

Corner common to sections

5, and 6

Corner consists of a Cedar post (not) in place

State condition good

Dimensions above ground 5x5x42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4	S	1/4	S
	6		5
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S			

Species Brich

Diameter 12"

Bearing S13°W

Distance 0.07

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Handwritten signature of J. Asst. to Tech.

(Signature)

Jr. Asst. to Tech.


(Title)

2/28/38

(Date)

Corner again.
 12" cedar N 15°W about 10 links
 blazed 4 sides, with initials HWH cut
 in west side with axe. Corner is on
 borderline between 3b and brush types.

Metal Location Poster is on a Birch Bearing
 tree 12 inches diameter, on the
 side of
 from which this Corner bears
 N 13°E
 0.07
 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture

C-5

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 W. 4th p. Mer.

1/4

Corner common to Sections

5, and 6

Corner consists of a Cedar post (not) in place

State condition good

Dimensions above ground 5x5x42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

4	3	4	3
	6		5
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

4			
S			

Species Birch

Diameter 12n

Bearing S130

Distance 0.07

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

[Handwritten Signature]

(Signature)

2/28/36 (Date)

Jr. Asst. to Tech. (Title)


C-5

12" cedar N 15° W about 10 links
 blazed 4 sides, with initials HHH cut in
 in west side with axe. Corner is on
 borderline between 3b and brush types.
 Corner again.

Give any further facts which will aid in finding this
 chains distant.

0.07
 from which this Corner bears
 N 13° E
 side of

tree 12 inches diameter, on the
 Metal Location Poster is on a Birch Bearing



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

C-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 W. 4th P. Mer.

1/4

Corner common to Sections

5, and 6

Corner consists of a Cedar post (not) in place

State condition good

Dimensions above ground 5x5x42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

4	S	4	S
	6		5
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

4 S			

Species Birch

Diameter 12"

Bearing S13°W

Distance 0.07

Do you believe this to be a genuine Land Office Corner? yes

If not, why?


[Handwritten Signature]

(Signature)

2/28/38 (Date)

Jr. Asst. to Tech. (Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a Birch Bearing

tree 12 inches diameter, on the

side of

from which this Corner bears

N 15° E

chains distant.

0.07

Give any further facts which will aid in finding this

Corner again.

12" cedar N 15° E about 10 links

blazed 4 sides, with initials HHH cut in west side with axe. (Corner is on

borderline between 3b and brush types.

5-5