

U. S. Department of Agriculture  
FOREST SERVICE

E-11

CHIPPEWAGON NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57<sup>N</sup> R. 26<sup>W</sup> 4<sup>th</sup> Mer.1/4 Corner common to Sections  
4, and 9Corner consists of a balsam post (with iron pin) in place  
State condition goodDimensions above ground post 36" dia 10 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

5		5	
4		9	

N W S E


NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.

5 4			
B.T.			

Species MapleDiameter 9"Bearing S. 56° EDistance 69 li.Do you believe this to be a genuine Land Office Corner? NO

If not, why? \_\_\_\_\_

Surveyed by CountyErnest Perry

(Signature)

7-13-34

(Date)


Field asst.

(Title)

E-91

Corner again.  
A CORNER TO SEC 9 & 9  
T 57N. R 6W 9TH MER. IS  
LOCATED IN THICK SECOND  
GROWTH MAPLE & HAZEL BRUSH

Metal Location Poster is on a  
tree 9 inches diameter, on the N.W.  
side of tree  
from which this Corner bears  
N. 56° W. 69 links chains distant.  
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T 57N. R 6W 9TH Mer.

U. S. Department of Agriculture  
FOREST SERVICE

E-11

**Chippewa NATIONAL FOREST**  
**CORNERS OF THE PUBLIC SURVEY**

T. 52 N. R. 26 W. 9<sup>th</sup> Mer.

1/4 Corner common to Sections  
4, and 9

Corner consists of a balsompast (not) in place  
(iron pin)  
State condition good

Dimensions above ground post 36 pin 10 inches  
Sketch groove  letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

S 4		S 9	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 4		S 9	
B.T.			

Species Maple  
Diameter 3"  
Bearing S 56° E  
Distance 69 li.

Do you believe this to be a genuine Land Office Corner? YES  
If not, why? \_\_\_\_\_

Ernest Perry  
(Signature)

Field 9554  
(Title)

7-13-34  
(Date)

E-91

1/4 CORNER TO SEC 49  
T 57N R 6W 4th N. 15 locat-  
ed in this growth of  
Maple & hazel brush

Corner again.

Give any further facts which will aid in finding this


6 1/2 inch chains distant.

from which this Corner bears N. 56. W.

side of tree

tree 9 inches diameter, on the N.W.

Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T 57N R 6W 4th Mer.

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

E-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

14  
4 Corner common to Sections

and 9  
Corner consists of a 4" Basem + iron pin. (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
A		9	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S A			
B.T			

Species Maple

Diameter 9"

Bearing S56°E

Distance 69 1/2

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner located by County resurvey.

(Signature)

(Date)

(Title)

193

1/4 corner to see 4x9  
I 57N R 26 W 4th Mer. is located  
in thick second growth Maple  
& hazel brush

Corner again.

Give any further facts which will aid in finding this


69 links chains distant.

from which this Corner bears N 56° W

side of tree

tree 9 inches diameter, on the NW

Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T. 57 R. 26 W. 4th Mer.