

Supervisor's copy

U. S. Department of Agriculture  
FOREST SERVICE

P  
C 11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N., R. 26 W., 4<sup>th</sup> Mer.


Center 1/4 Corner common to Sections  
4, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a triangular iron pin (not) in place  
State condition good - has 30" scribed guard stake

Dimensions above ground 6 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? no

If not, why? Evidently established by county surveyors.

Charles J. Knoblauch

(Signature)

July 23, 1937

(Date)

Junia Forester

(Title)

Corner is on south side of hill just north of swamp. It is near intersection of N 5, E 1/4 tract lines which are plainly visible at this time.

Corner again.

Give any further facts which will aid in finding this

chains distant.


0.47

From which this Corner bears S 70° W

side of tree

tree 10 inches diameter, on the SW

Metal Location Poster is on a Bloom tree



(Make sketch of topography near Corner)

T. 57N., R. 26W., 4th Mer.

Buy Lake  
camp copy

U. S. Department of Agriculture  
FOREST SERVICE

C-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N., R. 26 W., 4<sup>th</sup> Mer.  
center 1/4 Corner common to Section 4,  
—, and —

Corner consists of a triangular iron pin (not) in place  
State condition good - has 30" scribed guard stake

Dimensions above ground 6 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

~~700 bearing trees.~~

			5 5 7
			B.T.

Species \_\_\_\_\_ W. Pine  
 Diameter \_\_\_\_\_ 1 1/2"  
 Bearing \_\_\_\_\_ N 79° E  
 Distance \_\_\_\_\_ 119 links. (6)

Do you believe this to be a genuine Land Office Corner? No  
 If not, why? Evidently established by county surveyors.

Charles J. Knoblauch

(Signature)

Junior Forester

(Title)

July 23, 1937  
(Date)

11-7

B.T. found for this corner by A. Johnson 11/23/39

Corner is on south side of hill, just north of swamp. It is been investigated of N.S., E.W. & W. It is not given on plan of this time.

Corner again.

Give any further facts which will aid in finding this chains distant.


0.47

From which this corner bears S 40° W

side of tree

tree 10 inches diameter, on the SW

Metal Location Poster is on a Balsam fir



(Make sketch of topography near corner)

T. 57N., R. 26W., 9th Mer.