

U. S. Department of Agriculture
FOREST SERVICE

E-13

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEYT. 57 N. R. 26 W. 4th Mer.Section Corner common to Sections
3, 4, 9, and 10Corner consists of a dash post (not) in place
(iron pin)State condition good
Dimensions above ground post 3 1/2" pin 10 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S 4	S 9	S 10	S 3
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 4		S 10	
--------	--	---------	--

B.T.		B.T.	
------	--	------	--

Species dash w. birchDiameter 4" 4" pay take copyBearing S 85° E N 49° WDistance 98 li 135 liDo you believe this to be a genuine Land Office Corner? YES

If not, why? _____

Ernest Perry

(Signature)

7-13-34

(Date)


Field Ass't

(Title)

F-13

CORNER IS LOCATED IN THE
N.W. SIDE AS SMALL OSH SWAMP
Corner again.

Give any further facts which will aid in finding this
98 links chains distant.
from which this Corner bears N. 85° W.
side of TREE
tree 9 inches diameter, on the N.W.
Metal Location Poster is on a 6.05h



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

E-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. T57N. R. R6W. 4th Mer.

Section Corner common to Sections
3, 4, 9, and 10

Corner consists of a black ash post (not) in place
also iron pipe
State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S 4	S 9	S 10	S 3
--------	--------	---------	--------

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 4		S 10	
B.T.		B.T.	

Species black white

Diameter 4" 4"

Bearing S85°E N39°W

Distance 98 li 135 li

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

Ernest Curry

(Signature)

Field Ass't

(Title)


7-13-34

(Date)

E-13

CORNER IS LOCATED IN THE
N.W. SIDE OF SMALL ASH
SWAMP
Corner again.

Metal Location Poster is on a bush.
tree .4 inches diameter, on the N.W.
side of tree
from which this Corner bears N. 85° W
98 links chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

E-13

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th. Mer.

Section Corner common to Sections

3, 4, 9, and 10

Corner consists of a Black Ash + 1/2" iron pin (not) in place

State condition Good

Dimensions above ground 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S	S	S	S
4	9	10	3

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 4

--

S 10

--

BT

--

B.T.

--

Species Black Ash W. Birch

Diameter 4" 4"

Bearing S 85° E N 39° W

Distance .98 ch 1.35 ch

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner located by County

Survey.

(Signature)

(Date)

(Title)

E-13

Corner again.
 Corner located in the
 NW side of small ash swamp.

Give any further facts which will aid in finding this


98 links chains distant.

from which this Corner bears N 85° W

side of RR

tree 4 inches diameter, on the NW

Metal Location Poster is on a B. Ash



(Make sketch of topography near Corner)

Mer.

4

R. 26

T. 57