

**U. S. Department of Agriculture**  
**FOREST SERVICE**

N 14

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 57N R. 26W 4th Mer.

W 1/16 Corner common to Sections

Corner consists of a 1 1/2" Iron Pipe (not) in place  
5" scribed Post  
15 and 22

State condition Good

Dimensions above ground Post 40 Pipe 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

**CARDINAL POSITION**

**DIAGONAL POSITION**

<u>W 1/16</u>		<u>W 1/16</u>	
<u>5.15</u>		<u>5.22</u>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>B.T.</u>	<u>B.T.</u>		

Species Oak Basswood

Diameter 10" 14"

Bearing N86°W N83°E

Distance 56 lks 45 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by  
County Surveyor

Richard J. Johnson


(Signature)

2/2/190  
(Date)

Forest Foreman  
(Title)

(Make sketch of topography near Corner)

T. 52N R. 26W Mer. 4th



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

14  
N-10

**U. S. Department of Agriculture**  
**FOREST SERVICE**

*Chippewa* NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. *57N* R. *26W* 4th Mer.

*W 1/16* Corner common to Sections

Corner consists of a *5 1/2" inscribed Post* and *2.2*  
*1/2" Iron Pipe* (not) in place

State condition *Good*

Dimensions above ground *Post 90 Pipe 5* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>W 1/6</i>		<i>W 1/6</i>	
<i>5.15</i>		<i>5.22</i>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>B.T.</i>	<i>B.T.</i>		

Species *Oak* *Basswood*

Diameter *10"* *14"*

Bearing *N 86° W* *N 83° E*

Distance *561ks* *451ks*

Do you believe this to be a genuine Land Office Corner? *NO*

If not, why? *Records show it was set by*  
*County Surveyor*

*Arthur J. Johnson*  
(Signature)

*Squad Foreman*  
(Title)

*2/2/40*  
(Date)

N-14

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57N R. 26W Mer. 976

U. S. Department of Agriculture  
FOREST SERVICE

~~210~~  
N-14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4 Mer.

N 1/16 Corner common to Sections  
15, and 22

Corner consists of a iron pipe - cedar post (not) in place  
State condition good

Dimensions above ground 6 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>W 1/16</u>		<u>W 1/16</u>	
<u>S 15</u>		<u>S 22</u>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>W 1/16</u>		<u>W 1/16</u>	
<u>S 22</u>		<u>S 15</u>	
<u>BT</u>		<u>BT</u>	

Species M. sp. 12 birch  
Diameter 12" 11"  
Bearing S 24° W N 74° E  
Distance 38 Lks 113 Lks

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_

Edgar Parker  
(Signature)

Leah Foreman  
(Title)

9/25/34  
(Date)

N-14

Small square marked by  
200' E of base of this corner

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

N-14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W. 4th Mer.

W 1/2 Corner common to Sections

Corner consists of a <sup>15</sup> 3" <sup>and 23</sup> scribed post ~~1/2~~ Iron Pipe (set) in place

State condition Good

Dimensions above ground Post 10 Pipe 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

W 1/2		W 1/2	
3.15		3.22	


N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B.T.	B.T.		

Species Oak Basswood

Diameter 10" 14"

Bearing N86°W N83°E

Distance 561ks 451ks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by County Surveyor

Arthur J. Johnson

(Signature)

Special Foreman

(Title)

2/2/190

(Date)

-N-14

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57N R. 26W 4th Mer.