

U. S. Department of Agriculture
FOREST SERVICE

N-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 9th Mer.

1/4 Corner common to Sections

15 and 22
3" scribed Post
Corner consists of a 1/2" Iron Pipe with E. Head (not) in place

State condition Good

Dimensions above ground Post 30 Pipe 9 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
5.15		5.22	

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 5.15			
B.T.	B.T.		

Species Maple Maple

Diameter 6" 8"

Bearing N68°E S22°E

Distance 28 lks 32 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by
County Surveyor

Arthur J. Johnson

(Signature)

2/2/40

(Date)

Special Foreman

(Title)

N-15

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57N R. 26W Mer. 9H

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

N 15

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.

1/4 Corner common to Sections

Corner consists of a 1/2" ^{3" scribed post} ~~Iron pipe with elbow~~ (not) in place

State condition Good

Dimensions above ground Post 30 Pipe 9 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
S. 15		S. 22	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S. 15			
B.T.	B.T.		

Species Maple Maple

Diameter 8" 8"

Bearing 568°E 522°E

Distance 281ks 321ks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by

County surveyor

Arthur J. Johnson

(Signature)

2/2/40


(Date)

Special Foreman

(Title)

(Make sketch of topography near Corner)

T. 52N R. 26W 9th Mer.



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

N-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.

1/4 Corner common to Sections

Corner consists of a ^{15 and 22}
^{3" Scruled Post}
^{1/2" Iron Pipe with Elbow (not)} in place

State condition Good

Dimensions above ground Post 20 Pipe 9 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>515</u>		<u>5.</u>	
		<u>22</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>			
<u>5.15</u>			
<u>B.T.</u>	<u>B.T.</u>		

Species Maple Maple

Diameter 6" 8"

Bearing N68°E S22°E

Distance 28 lks. 32 lks.

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by

County surveyor

Arthur J. Johnson

(Signature)

Squad Foreman

(Title)


2/2/90

(Date)

N-15

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 52N R. 26W 4th Mer.