

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 52N R. 26W 9th Mer.

E 1/16 Corner common to Sections

Corner consists of a 3 1/2" scribed Post and 22
1/4" Iron Pipe (not) in place

State condition Good

Dimensions above ground Post 26 Pipe 9 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---------------|---|---------------|---|
| <u>E 1/16</u> | | <u>E 1/16</u> | |
| <u>5.15</u> | | <u>3.22</u> | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|-------------|---------------|--|--|
| | <u>E 1/16</u> | | |
| | <u>5.15</u> | | |
| <u>B.T.</u> | | | |

Species Maple Maple _____

Diameter 8" 8" _____

Bearing S 38° W N 46° E _____

Distance 19 lks 31 lks _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by

County Surveyor

Arthur J. Johnson

(Signature)

Land Surveyor

(Title)

2/2/90

(Date)

N-16

Corner again.

Give any further facts which will aid in finding the


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

17

R. 26W

T. 57N

U. S. Department of Agriculture
FOREST SERVICE

N-16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *57 N* R. *26 W* *4* Mer.
E 1/16 Corner common to Sections

15, and *22*

Corner consists of a *live pine wood post* (not) in place
State condition *good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---------------|---|---------------|---|
| <i>E 1/16</i> | | <i>E 1/16</i> | |
| <i>S 15</i> | | <i>S 22</i> | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|---------------|--|---------------|--|
| <i>E 1/16</i> | | <i>E 1/16</i> | |
| <i>S 15</i> | | <i>S 22</i> | |
| <i>B T</i> | | <i>B T</i> | |

Species *Maple* _____ *Maple* _____

Diameter *9"* _____ *11"* _____

Bearing *N 40° E* _____ *S 43° W* _____

Distance *24 1/2 Lks* _____ *13 1/2 Lks* _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Edgar J. Parker
(Signature)

9/20/34
(Date)

Lech Foreman
(Title)

9-16

Just over 550m from hill on East slope

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

No. 16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 9th Mer.E 1/4 Corner common to Sections_____, _____, 15, and 22
24 scribed Post
Corner consists of a 1/2" Iron Pipe (not) in placeState condition GoodDimensions above ground Post 26 Pipe 9 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--------------|---|--------------|---|
| <u>E 1/4</u> | | <u>E 1/4</u> | |
| <u>5.15</u> | | <u>5.22</u> | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--------------|--------------|--|--|
| | <u>E 1/4</u> | | |
| | <u>5.15</u> | | |
| <u>B. T.</u> | | | |

Species Maple Maple _____Diameter 8" 8" _____Bearing S38°W N46°E _____Distance 19.1kz 31.1kz _____Do you believe this to be a genuine Land Office Corner? NoIf not, why? Records show it was set byCounty SurveyorArthur J. Johnson

(Signature)


Squid Hansen

(Title)

2/2/40
(Date)

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 67N R. 26W 4th Mer.

E 1/6 Corner common to Sections

15, and 22
Corner consists of a 2" scribed Post
1/2" x 1/2" Iron Pipe (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|-------|--|-------|--|
| E 1/6 | | E 1/6 | |
| 5.15 | | 5.22 | |

| | | | |
|--|--|--|--|
| | | | |
| | | | |

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|-----|-------|--|--|
| | E 1/6 | | |
| | 5.15 | | |
| B.T | | | |

Species Maple Maple _____

Diameter 8" 8" _____

Bearing S38°W N46°E _____

Distance 19 lks 31 lks _____

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Record shows it was set by

County Surveyor


Arthur J. Johnson
(Signature)

2/2/90
(Date)

Edward J. Johnson
(Title)

9-16

Metal Location Poster is on a _____
 tree _____ inches diameter, on the _____
 side of _____ from which this Corner bears
 _____ chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 57N R. 26W 475 Mer.