

U. S. Department of Agriculture
FOREST SERVICE

chipewea NATIONAL FOREST *M 17*

CORNERS OF THE PUBLIC SURVEY

T. *57 N* R. *26 W* *4th* Mer.

S 1/4 Corner common to Sections
....., *14*, and *15*

Corner consists of a *4" Asper post* (not) in place
State condition *Good*
12" iron pipe

Dimensions above ground *36" post, 6" pipe* Inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>5</i>		<i>5</i>
	<i>1/4</i>		<i>1/4</i>
N	W	S	E

<i>?</i>			
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<i>5</i>		<i>5</i>
	<i>15</i>		<i>14</i>
	<i>BT</i>		<i>BT</i>

Species *Balsam* *Spruce*

Diameter *10"* *6"*

Bearing *N 12° E* *S 25° E*

Distance *11.1 Ks.* *45.1 Ks.*

Do you believe this to be a genuine Land Office Corner? *YES*

If not, why?

K. L. R. ?
(Signature)

7-11-35
(Date)


(Title)

Corner again.
Corner is on North West
side of 76 swamp

Give any further facts which will aid in finding this
11 1/2 chains distant.

From which this Corner bears
side of tree

tree 10 inches diameter, on the SW
Metal Location Poster is on a Balsam



(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 47 1/2 Mer.

U. S. Department of Agriculture
FOREST SERVICE

M-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.
S 1/16

Corner common to Sections
14, and 15

Corner consists of a 4" ASPEN post (new) in place
State condition Good

Dimensions above ground 36" post 6" pipe

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S // // 16		S // // 16
--	---------------------	--	---------------------

--	--	--	--

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 15		S 14
	BT		BT

Species Balsam Spruce
 Diameter 10" 6"
 Bearing N 12° E S 25° E
 Distance 11.1 Ks 4.5 Ks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

K. D. P.
(Signature)


7-11-35
(Date)

(Title)

M-17

Corner again.
Corner is on North West
side of 76 swamp

Metal Location Poster is on a Balsam
tree 10 inches diameter, on the SW
side of 76
from which this Corner bears S 12° W
11/15 chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4-6 Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

A-17
 M-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.
 S 1/16 Corner common to Sections

14, and 15

Corner consists of a 4" Aspen post (and) in place


State condition 1/2" 5' of pipe
 8' 0" 0"

Dimensions above ground 36" post 6" splices

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balsam Spruce

Diameter 10" 6"

Bearing N12°E S25°

Distance 11.1ks. 45.1ks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

King
 (Signature)

7-11-35
 (Date)

(Title)

M-17

Corner again.

Give any further facts which will aid in finding this chains distant.

From which this Corner bears side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.