

U. S. Department of Agriculture

FOREST SERVICE

*Chippewa* NATIONAL FOREST *Posted. H17*

CORNERS OF THE PUBLIC SURVEY

T. *57 N* R. *26 W* --- *4th* Mer.

----- *S 1/16* ----- Corner common to Sections  
-----, -----, *10*, and *11*-----

Corner consists of a *3" Spruce (not)* in place  
State condition *good (1" iron pipe 6")*

Dimensions above ground *3* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	10		11
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S		S
	10		11
	B.T		B.T

Species ----- *2 AM* ----- *N. Pine*

Diameter ----- *8"* ----- *8"*

Bearing ----- *N 32° E* ----- *S 55° E*

Distance ----- *51 Li* ----- *30 Li*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? -----


*Erwin Meagher*  
(Signature)

*12-20-34*  
(Date)

*Field Ass't*  
(Title)

Corner again.  
HAND Rolling heavy  
Hazel Nipper brush

Give any further facts which will aid in finding this  
51 ft. ~~within~~ distant.  
from which this Corner bears  
side of tree  
tree 8 inches diameter, on the S. W.  
Metal Location Poster is on a T.A.M.



(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 4th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

H-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4<sup>th</sup> Mer.

S 1/16 Corner common to Sections

10, and 11

Corner consists of a 3" Spruce (not) in place

State condition good 1" iron pipe 6"

Dimensions above ground 3' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 10		S 11
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 10		S 11
	BT		BT

Species TAM N. Pine

Diameter 8" 8"

Bearing N32°E S55E

Distance 51.51' 30.41'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Emin Mearns  
(Signature)

12-20-34  
(Date)

Field Ass't  
(Title)

H-17

Land Rolling heavy  
hazel underbrush

Corner again.

Give any further facts which will aid in finding this


5171 chains distant.

from which this Corner bears S 32° W

side of tree

tree 8 inches diameter, on the S W

Metal Location Poster is on a T 9 m.



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

H-17

CHIPPEWA NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4<sup>th</sup> Mer.

S 1/16 Corner common to Sections  
-----, -----, 10, and 11-----

Corner consists of a 3" spruce (not) in place

State condition good (1" iron pipe 6")

Dimensions above ground 3' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 10		S 11
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 10		S 11
	BT		BT

Species ----- tam ----- N. pine

Diameter ----- 8" ----- 8"

Bearing ----- N 32° E ----- S 55° E

Distance ----- 51 li. ----- 30 li. (C)

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

E. Min. Wheeler  
(Signature)

12-20-34  
(Date)

Field Ass't  
(Title)

H-17

band rolling heavy  
hazel under brush

Corner again.

Give any further facts which will aid in finding this


51 ft. chains distant.

from which this Corner bears S 32° W

side of tree

tree 8 inches diameter, on the S W

Metal Location Poster is on a Tam.



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.