

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

#3 1/16 Corner common to Sections

11, and 10

Corner consists of a 3" BALSAM (not) in place

State condition good (1" iron pipe 8")

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 3		# 3	
S 11		S 11	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			# 3 S 11
			B.T.

Species _____ W. PINE

Diameter _____ 18"

Bearing _____ S 74° E

Distance _____ 11 Li

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

12-21-34 _____

(Date)

(Signature)

Erwin Meagher
Field ass't

(Title)

LAND LEVEL, SECOND GROWTH AS PER

Corner again.

Give any further facts which will aid in finding this

corner distant.


11-71

from which this Corner bears N 74° W

side of tree

tree 18 inches diameter, on the N.W.

Metal Location Poster is on a W. PINE



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

F-18

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.# 3 1/16 Corner common to Sections-----, -----, 11, and -----Corner consists of a 3" Balsam (~~not~~) in placeState condition good (1" iron pipe 8")Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 3		# 3	
S 11		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			# 3 S 11
			BT

Species ----- W. pineDiameter ----- 18"Bearing ----- S 77° EDistance ----- 11 LI.Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

Erwin McHugh
(Signature)

12-21-34
(Date)Field Ass't.
(Title)

F-18

grows with aspens
second level, second

Corner again.

Give any further facts which will aid in finding this

11 1/2 chains distant.

from which this Corner bears


N74°W

side of Tree

tree 18 inches diameter, on the

NW

Metal Location Poster is on a W Pine



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

F-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.
NW (# 3) 1/16 Corner common to Sections
_____, _____, 11, and _____

Corner consists of a 3" Balsam (not) in place
State condition good (1" iron pipe 8")
Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 3		# 3	
S 11		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			# 3
			S 11
			BT

Species _____ W. Pine
Diameter _____ 1 1/2"
Bearing _____ S 74° E
Distance _____ 11 LL ©

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Emin Mather
(Signature)

12-21-34
(Date)

Field Ass't
(Title)

F-18

7 and level, second growth aspen

Corner again.

Give any further facts which will aid in finding this

chains distant.

N 74° W

from which this Corner bears

side of Tree

tree 18 inches diameter, on the N. W.

Metal Location Poster is on a W. P. M. S.

	Sec.		Sec.
	Sec.		Sec.
			36

(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.