

U. S. Department of Agriculture
FOREST SERVICE

H-19

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.
CS (# 6) 1/16 Corner common to Sections
-----, -----, 11, and -----

Corner consists of a 3" ASPEN (root) in place
State condition good (1" iron pipe)

Dimensions above ground 3' high inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 6		# 6	
S 11		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	# 6 S. 11		
	B.T		

Species ----- ASPEN -----
Diameter ----- 6" -----
Bearing ----- S 76° W -----
Distance ----- 42 Li -----

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

Emin Meagher
(Signature)

12-7-34
(Date)

Field ass't
(Title)

H-19

LAND Level, Second
grown with ASPEN

Corner again.

Give any further facts which will aid in finding this


42.0 ~~feet~~ distant.

from which this Corner bears N 76° E

side of tree

tree 8 inches diameter, on the N.E.

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 474 Mer.

U. S. Department of Agriculture
FOREST SERVICE

H-19

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.
5C (#6) 1/16 Corner common to Sections
_____, _____, 11, and _____

Corner consists of a 3" ASPEN (not) in place
State condition good (1" iron pipe 8")

Dimensions above ground 3' high inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 6		# 6	
S 11		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	# 6 S. 11		
	B.T		

Species _____ ASPEN _____

Diameter _____ 6" _____

Bearing _____ S 76° W _____

Distance _____ 42 Li _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Emin Meagher
(Signature)

12-7-34
(Date)

Field ass't
(Title)

H-19

LAND Level,
SECOND growth
ASPEN

Corner again.

Give any further facts which will aid in finding this

42 ft. ~~chain~~ distant.


N 76.0 E

from which this Corner bears

side of tree

tree 6 inches diameter, on the N.E.

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 474 Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST H 19 posted

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.

6 1/16 Corner common to Sections

-----, -----, 11, and -----

Corner consists of a 3" ASPEN (net) in place

State condition good (1" iron pipe 8")

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 6		# 6	
S 11		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	# 6 S 11		
	BT		

Species ----- ASPEN -----

Diameter ----- 6" -----

Bearing ----- S 76° W -----

Distance ----- 42 Li -----

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

12-7-34 -----

(Date)

(Signature)

Emin Meagher
Field Ass't

(Title)

LAND Level, Second
gro with ASPEN

Corner again.

Give any further facts which will aid in finding this


42 L! chains distant.

from which this Corner bears N76.E

side of tree

tree 8 inches diameter, on the N.E

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.