

Supervisor
C 97

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

A 24

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W. 4 Mer.
E 1/16

Corner common to Sections
1 T57 R27, and 36 T58 R27

Corner consists of a 3" Aspen (not) in place


State condition Placed Feb 9 1937

Dimensions above ground Possibly 60 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W.P. stump W.P. stump

Diameter 30" 36"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No
If not, why? Did not locate 1/16 corners

James C. ...

(Signature)

Feb. 9, 1937
(Date)

Jr. Forester P. S.
(Title)

as shown in diagram.

as one B.T. is on each side of T.T.

Corner should be in T.T. #570

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57N. R. 27W. Mer. 4