

U. S. Department of Agriculture
FOREST SERVICE

A-B-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 W. 4 CH Mer.

M. C Corner common to Sections

.....,, 1, and 2

Corner consists of a 4-IN. Spruce (not) in place

State condition good

Dimensions above ground 2 feet inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 2		S 1
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 2		S 1
	B.T.		B.T.

Species Spruce Spruce

Diameter 5 IN 5 IN

Bearing S 52° W S 47° E

Distance 16-1KS 13-1KS 0

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Erwin Meagher

(Signature)

Field Ass't

(Title)

10-31-34

(Date)

A-B-21-

M.C. is on S. side of
small lake of about
15 acres in size
5 small spruce swamp
borders same

Corner again.

Give any further facts which will aid in finding this


56-1/2 chains distant.

from which this Corner bears N 70° W

side of tree

7 inches diameter, on the N.W.

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 52 N. R. 21 W. 4th Mer.

U. S. Department of Agriculture

FOREST SERVICE

posted

Chippewa NATIONAL FOREST A-B 21

CORNERS OF THE PUBLIC SURVEY

T. *57 N.* R. *26 W.* *4th* Mer.

M.C. Corner common to Sections
 _____, _____, *1*, and *2*

Corner consists of a *4 in spruce* in place
 State condition *good*

Dimensions above ground *2 feet* inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>3</i>		<i>1</i>
<i>2</i>			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<i>S.</i>		<i>S.</i>
	<i>2</i>		<i>1.</i>
	<i>B.T.</i>		<i>B.T.</i>

Species	<i>spruce</i>	<i>spruce</i>
Diameter	<i>5-in.</i>	<i>5-in.</i>
Bearing	<i>S. 52° W</i>	<i>S. 49° E</i>
Distance	<i>16-1ks</i>	<i>13-1ks</i>

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Erwin Meagher

(Signature)

10-31-34
 (Date)

Field Ass't
 (Title)

M.C. IS ON S. SIDE
OF SMALL LARCE OF
OF ABOUT 15 ACRES
IN SIZE SMALL
SPACE SWAMP
BORDERS SWAMP

Corner again.

Give any further facts which will aid in finding this


56-115 chains distant.

From which this Corner bears N. 70° W.

side of tree

tree 7 inches diameter, on the N.W.

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 7th-Mer.

U. S. Department of Agriculture
FOREST SERVICE

A-10-21

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W Mer. 4Meander Corner common to Sections-----, -----, 1, and 2-----Corner consists of a 4" Spruce (not) in placeState condition good-----Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		s
	2		1

N W S E

NW SW SE NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 2		S 1

Species Spruce SpruceDiameter 5" 5"Bearing S 52° W S 44° EDistance 16 lks. 13 lks.Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

Ervin Meagher

(Signature)

Field Asst

(Title)


10-21-24

(Date)

A-B-21

Corner again.
M.C. is on S. side of small
Lake (about 15 Acres) small stream
same borders same

Metal Location Posters on a
tree 7. inches diameter, on the
side of tree
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 57N R. 26W Mer. 4