

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

G-H-19

CHIPPewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

Corner common to Sections
 _____, _____, 11, and _____

Corner consists of a 3" ASPEN (not) in place
 State condition good

Dimensions above ground 2' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	M C S 11		M C S 11
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.C. S. 11			
B.T.			

Species N. Pine

Diameter 12"

Bearing N 14° W

Distance 8. Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

E. W. Meagher
 (Signature)


12-7-34
 (Date)

Field Ass't
 (Title)

61-H-9

Corner again.
LAND ROLLING, SECOND
GROWTH ASPEN

Metal Location Poster is on a N. PINE
tree 12 inches diameter, on the
side of tree
from which this Corner bears
80 L. ~~chain~~-distant.
S. 14° E
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 4th Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

East of
6419

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 W. 4th Mer.

M. C. Corner common to Sections

, 11, and

Corner consists of a 3" ASPEN (not) in place

State condition good

Dimensions above ground 2' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	MC		MC
	S 11		S 11
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.C.			
S. 11			
B.T.			

Species N. PINE

Diameter 12"

Bearing N 14° W

Distance 8.2 LI

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

Erwin Meagher

(Signature)

12-7-34

(Date)

Field Ass't


(Title)

Corner again.
LANDROLLING, SECOND
grows with aspen

Give any further facts which will aid in finding this
80 ft. ~~thence~~ distant.

From which this Corner bears S 14° E

side of tree
tree 1 1/2 inches diameter, on the
Metal Location Poster is on a
N. PINE N.S.E.



(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 4th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

G-H-19

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4 EA Mer.



M.C. Corner common to Section
11, and

Corner consists of a 3" ASPEN (not) in place
State condition good

Dimensions above ground 2' high inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. PINE

Diameter 12"

Bearing N. 14° W

Distance 80 L'

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

E. Min. Meagher
(Signature)

12-7-34
(Date)

Field ass't
(Title)

6-11-19

LANDROLLING SECOND GROWTH ASPEN

Corner again.

Give any further facts which will aid in finding this


80 LI. ~~chain~~ distant.

from which this Corner bears S. 14° E

side of tree

tree 12 inches diameter, on the S.E

Metal Location Poster is on a N. PINE



(Make sketch of topography near Corner)

T. 57N R. 26W 4th Mer.